

# **SAS Superstructure**

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans **Run date** 21-Nov-14 **Time** 11:09 AM

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

# Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 222 Const Calendar Day: 449 Date: 01-Dec-2010 Wednesday Inspector Name: Wilcox, Jason Title: Transportation Engineer

Inspection Type: Intermittent

Shift Hours: 06:30 am 05:00 pm Break: 00:30 Over Time: 02:00

Federal ID: Location:

Reviewer: Jefferson, Paul Approved Date: 30-Jan-14 Status: Approved

Weather

 Temperature
 7 AM
 40 - 50
 12 PM
 50 - 60
 4PM
 50 - 60

 Precipitation
 Condition
 Clear

Working Day 🗸 If no, explain:

Diary:

### **General Comments**

Partly cloudy and cold

#### FIELD WORK:

See Thanh Le's diary for details on the W-Line and David Bradd's for the E-Line.

- •Visited the field first thing to take a look at the bolts on the CB 11/9E stiffeners. David Bradd called me yesterday to let me know that there may be some that are not long enough. I observed that some of the bolts were not flush with the face of the nut. I took pictures and brought them in to show Paul Jefferson. He agreed that they were not flush. I called Dan Hester from ABF to let him know of the locations and he said he would check them out and get back to me.
- •While in the field I took pictures of Punchlist items #1709 (cable tray install; not done), #1245 (3E/4E L.D. offsets), #406 (Suspender Bracket at PP24W, not 24E)
- •Bolt testing for Suspender Bracket at PP24W and West angle plate for CW22)

### OFFICE WORK:

Prepare for hosting the Safety Meeting tomorrow

Accrued 2 hours of overtime documenting and covering the Contractor's hours.